CARLO GAVAZZI

Sx Tool Download

Instructions



Download the **Sx Tool** from this link:

We always suggest to upgrade your system to the latest software release

Scarica Sx Tool da questo link:

Consigliamo di effettuare sempre l'aggiornamento del sistema alla versione

più recente del software

Télécharger le Sx Tool de ce lien :

Nous vous suggérons de toujours mettre à jour votre système avec la plus récente

version du logiciel

Descargar el Sx Tool desde este enlace:

Le sugerimos que actualice siempre su sistema a la última versión del software



Laden Sie die Sx Tool, von diesem Link:

Wir empfehlen Sie, Ihr System immer auf Software-Version neueste aktualisieren

!! Tips & Tricks

See the pages below Vedere le pagine seguenti Voir les pages suivantes Véase a continuación Siehe unten

History

7.7.3 19022701- R888 Release name:

SA Tool Download:

SB Tool SBP Tool SH Tool

7.6.31 18110702- R871 Release name:

Download: **SA Tool**

SB Tool **SBP Tool SH Tool**

Release name: 7.6.3 18102201- R868

Download: SA Tool

SB Tool SBP Tool SH Tool

Release name: 7.5.31 18032701- R827

Download: **SA Tool**

SB Tool **SH Tool**

7.5.3 18020903 - R811 Release name:

Download SA Tool

SB Tool SH Tool

Release name: 7.4.31 17112401-R779

Download SA Tool

SB Tool SH Tool

7.4.3 171111702 R775 Release name:

Download

SB Tool SH Tool

Release name: 7.3.3 17111001 - R770

Download **SBP Tool**

6.5.32 17062101-R725 Release name:

Download **SB Tool SH Tool**

6.5.31 17060503-R721 Release name:

Download **SB Tool**

SH Tool

6.5.3 17052201-R715 Release name:

Download

SB Tool SH Tool

Release name: 6.3.3 16122201 - R597

Download **SB Tool**

SH Tool

Older versions are available here: **Download link**



Tips & Tricks

Index

S	mart building system Sx2WEB24	2
	Energy save timer is not reloaded when the light level is above the threshold	. 2
	Reports created from web App shows wrong month	. 3
	Not possible to edit calendar activity from the web App	. 4
	Not possible to log additional function status in the Database	. 4
	Wrong icons shown in the web App	. 5
	Not possible to scan the DALI network "subnet not found" error message appears	. 6
	Dupline temperature regulation function deactivates the heating setpoint	. 7
	Calendar activities cannot be added	. 8

Smart building system Sx2WEB24

Energy save timer is not reloaded when the light level is above the threshold


Problem description

The automation of the light function puts together lux meter, PIR and energy save timer. When the lux value is below the threshold and the PIR detects movement, the light goes on. At this point the lux value goes above the threshold and the energy save timer is not reloaded anymore, therefore the light goes off even if there is presence in the room.


Solution

Create an external analogue comparator that is used to define the "dark" condition.

Use the comparator function as input of a multigate "AND" function combined with the *movement signal* of the PIR sensor.




Use the multigate as input signal (On/Off Signals tab) of the Light function.





In the light function, add the presence signal of the PIR.



Reports created from web App shows wrong month

Problem description

In the web app *Reports* window, you have created a template for a report in October 2018 but when you save and create the report, November 2018 data logs are shown.

Solution

You may face this issue if you run a Web browser with Norwegian or Chinese language.

The problem is due to the wrong default language that is automatically set by the Web App.

To fix this issue, navigate the web App settings, select the English language, then select again the correct language and save to apply the settings.





Not possible to edit calendar activity from the web App

Problem description

When you try to edit a calendar activity from the Web App, you get an error and the login page is shown.

Solution

You may face this issue if you run a Web browser with Norwegian or Chinese language.

The problem is due to the wrong default language that is automatically set by the Web App.

To fix this issue, navigate the web App settings, select the English language, then select again the correct language and save to apply the settings.



Not possible to log additional function status in the Database


Problem description

In the Database window, the additional function status of a function is not available and it is not possible to log them into the Database of the system.


Solution

This procedure has to be followed in order to log the addition status of the functions in the Database (for example the additional status of a math function).

 Add to the project one Analog Output function for each additional status not available in the Database.




b. Add to the analogue output function the additional status of the math function.






c. Change the name of the Analog Output functions in order to have a clear description of the additional status (es. function_name" + "additional_status").



d. In the DB Manager add to the Database the Analog Output function.




Wrong icons shown in the web App

Problem description

After a firmware upgrade of the system the icons in the web App are not correct (the icons are messed up or missing).

Solution

The error is due to the cache of the web browser, the issue will be resolved cleaning the cache and logging-in again in the web App.





Not possible to scan the DALI network "subnet not found" error message appears

Problem description

After adding the DALI module to the project, from the DALI module discovery window, the user tries to find the ballast connected, but when the search button is pressed, the discovery ends immediately with an error "Subnet not found"




Resolution

This is the list of steps to follow to fix the issue

1. Delete the SB2DALI module from the project and add it again after a discovery.



2. Add a multigate function and use the presence diagnostic signal of the DALI module as input signal of the function.



- 3. Write the configuration to the Sx2Web controller.
- 4. When the DALI module is programmed it should be possible to scan the DALI modules from the module "search window".



Dupline temperature regulation function deactivates the heating setpoint

Problem description


When the advanced field Cooling is selected in the Dupline temperature regulation and there is no output signal used, the temperature function activates the cooling set point every time the configuration file is sent to the controller, consequently the heating function goes from heating T1 to TOFF and stops heating.


This problem happens also when the controller restarts because the system loads the configuration at startup and the cooling setpoint is activated.

Resolution

In the advanced menu "available output status" the signal temperature regulation. Cooling should be deactivated.

The advanced menu "Cooling" should be unselected.







Calendar activities cannot be added

Problem description

When a calendar activity is going to be added either in the *Local calendar* of the functions where it is available in the *Advanced* options, or in the *Global calendar* function, after filling the required fields the *Confirm* button cannot be pressed (this is shown in grey colour).

Resolution

This happens if at least one of the following conditions is verified:

