

Pressure setting, ex-factory

Part no. +PMIN(*)/PMAx(*)
Catalog No. 203948
Alternate Catalog No. -

Delivery program

Product range		Accessories
Basic function		Pressure setting
		Article no. for ordering with basic unit
For use with		MCS, MCSN
Notes		
Standard setting of the cut-in and cut-out pressures		
When ordering, the part no. must include the following details:		
1st wildcard Δ cut-in pressure in bar		
2nd wildcard Δ cut-out pressure in bar		
The following tolerance ranges apply to the cut-in and cut-out pressures:		
up to 5 bar: ± 0.2 bar		
5 - 6.5 bar: ± 0.3 bar		
6.5 - 25 bar: ± 0.4 bar		
Notes Ordering example		
<ul style="list-style-type: none"> Desired part no.: MCS4 Required cut-in pressure in bar: 2.2 Required cut-out pressure in bar: 3 		
A maximum of one decimal place after the comma is possible with the pressure definition.		
The correct type is:		
MCS4 + PMIN(2.2)/PMAx(3.0)		
Notes Article no. for ordering with basic unit		

Design verification as per IEC/EN 61439

Technical data for design verification		
Operating ambient temperature max.	°C	70

Technical data ETIM 7.0

Low-voltage industrial components (EG000017) / Accessories for low-voltage switch technology (EC002498)		
Electric engineering, automation, process control engineering / Low-voltage switch technology / Component for low-voltage switching technology / Component for low-voltage switch technology (accessories) (ecl@ss10.0.1-27-37-13-92 [AKN570013])		
Type of accessory		Other

Approvals

Product Standards		CSA-CC22.2 No. 14
CSA File No.		12528
CSA Class No.		3211-06
North America Certification		CSA certified