

SITRANS P210 Transmitters for pressure and absolute pressure for low-pressure applications Non-linearity: 0,25 percent (typically) wetted parts material: stainless steel plus sealing material; non-wetted parts material: stainless steel Measuring range for gauge: 0 to 160 mbar, Overload- pressure 400 mbar OUTPUT SIGNAL: 0 TO 5 V; THREE-WIRE CONNECTION, POWER SUPPLY DC 12 TO 33 V without explosion protection Electrical connection: Cable quick connector PG9 (not with explosion protection) Process connection: 1/2"-14 NPT male Sealing material between sensor and housing: Neoprene (CR) Standard version

## Further information

**Information- and Downloadcenter (Catalogs, Brochures,...)**

<http://www.siemens.de/industrial-controls/catalogs>

**Industry Mall (Online ordering system)**

<https://mall.industry.siemens.com>