

SITRANS P210 Transmitters for pressure and absolute pressure for low-pressure applications Non-linearity: 0,25 percent (typically) wetted parts material: stainless steel plus sealing material; non-wetted parts material: stainless steel Measuring range for gauge: 0 to 250 mbar, Overload- pressure 1000 mbar Output Signal: ratiometric 10 ... 90 % without explosion protection Electrical connection: Connection via mounted cable, 2m (not with explosion protection) Process connection: 7/16"-20 UNF female Sealing material between sensor and housing: Perbunan (NBR) Standard version

## Further information

**Information- and Downloadcenter (Catalogs, Brochures,...)**

<http://www.siemens.de/industrial-controls/catalogs>

**Industry Mall (Online ordering system)**

<https://mall.industry.siemens.com>